


DBI-SALA Delta II harness



The NASC have recently been advised by one of its members, that they have been experiencing issues with the DBI-SALA Delta II harness. The DBI-Delta II harness was a replacement for the SALA Surefit harness. The issue has been in keeping proper shoulder adjustments, the result being that the harness fit becomes loose over the course of the working day. After a thorough investigation by Capital Safety it has been agreed that the issue can best be resolved by moving to another Capital Safety Group harness that is a better fit for the type of work carried out by scaffolders, which includes excessive amounts of bending, climbing and moving about. Members should be aware that these harnesses are now being voluntarily replaced by an alternative model – the Protecta Flexa harness. The Flexa incorporates elasticised shoulder straps that allow for increased flexibility and comfort, yet offers the same protection in the event of a fall that a traditional web based harness does.

For more information on these harnesses we recommend contacting Capital Safety Group directly via: www.capitalsafety.com